



Figure 1 – Plaque on east abutment wall



Figure 2 – Los Padres Dam and Reservoir





Figure 3 – Looking south to dam face



Figure 4 - Looking south to plunge pool and Behavioral Guidance System (BGS) pipe outlet





Figure 5 – Bailey Bridge and plunge pool at end of spillway





Figure 6 – looking east at Behavioral Guidance System exit



Figure 7 – Existing weir fishway (Denil ladder) entrance in plunge pool





Figure 8 – looking downstream from top of dam to spillway



Figure 9 – east abutment





Figure 10 – looking east along top of dam toward spillway



Figure 11 – looking west along top of dam from mid-point of dam to west abutment





Figure 12 – Looking upstream (south) to west abutment



Figure 13 – boulders placed to stabilize downstream face





Figure 14 – Behavior Guidance System at dam spillway



Figure 15 – Looking west at spillway w/BGS anchored to left wall and dam access road in background.



Figure 16 – top of foreset slope





Figure 17 – upper reservoir silt and organic deposits



Figure 18 – siltation at upper end of reservoir





Figure 19 – upstream end of inundation zone



Figure 20 – debris in reservoir, January 1995