

Figure 1 – Plaque on east abutment wall



Figure 2 – Los Padres Dam and Reservoir



Figure 3 - Looking south to dam face



Figure 4 - Looking south to plunge pool and Behavioral Guidance System (BGS) pipe outlet




Figure 5 – Bailey Bridge and plunge pool at end of spillway



Figure 6 – looking east at Behavioral Guidance System exit



Figure 7 – Existing weir fishway (Denil ladder) entrance in plunge pool



Figure 8 – looking downstream from top of dam to spillway



Figure 9 – east abutment



Figure 10 – looking east along top of dam toward spillway



Figure 11 – looking west along top of dam from mid-point of dam to west abutment



Figure 12 – Looking upstream (south) to west abutment



Figure 13 – boulders placed to stabilize downstream face



Figure 14 – Behavior Guidance System at dam spillway



Figure 15 – Looking west at spillway w/BGS anchored to left wall and dam access road in background.



Figure 16 – top of foreset slope



Figure 17 – upper reservoir silt and organic deposits



Figure 18 – siltation at upper end of reservoir




Figure 19 – upstream end of inundation zone



Figure 20 – debris in reservoir, January 1995



Above: December 12, 1988 Below: October 15, 2007



Figure 21 – reservoir comparison



Figure 22 – slide in upper Carmel River above Los Padres Dam

