

EXHIBIT 3-A

BID ADDENDUM 2 -- June 19, 2018

**CARMEL RIVER BANK STABILIZATION
AT RANCHO SAN CARLOS ROAD**

The items below are to be incorporated into the Notice Inviting Sealed Bids and costs shown on the Bid Form.

Item 8 – Access and staging at site (Bid Items 1, 2, 3, 4) – see also Figures below

- 1.1 Remove dead pine tree adjacent to fence on Rancho San Carlos Road and dispose offsite
- 1.2 Remove approximately 20 feet of fence on Rancho San Carlos Road
- 1.3 Install two 10-ft. gates with lock; match gate style to existing fence style; gates to open inward to staging area
- 1.4 Install temporary asphalt apron (20 ft. x 20 ft.); contractor to patch or fill as necessary to maintain a smooth transition from the temporary apron to Rancho San Carlos Road; remove as directed after project completion
- 1.5 Clear and grub inside fence to limits of cottonwood; remove cypress tree, poison oak, blackberry, fennel and other vegetation to allow access into the site and staging of materials
- 1.6 Protect live cottonwood and oak trees on perimeter of staging site with temporary high visibility fencing
- 1.7 Dispose cleared vegetation off-site
- 1.8 Install temporary high visibility fencing to limit access to sensitive species (Santa Barbara sedge) as shown on Sheet 3.0
- 1.9 Protect 36-inch cottonwood at access ramp; remove large limb from 36-inch cottonwood that blocks access to streambank; remove 18-inch cottonwood blocking access ramp; cottonwood pieces of 10-ft. or greater may be stockpile and placed into the channel bottom at the end of construction.
- 1.10 Hydroseed staging area at end of construction

Ahmet Gulcu



6-28-2018