



General Managers Report Item 10

Conditions on the River

David J. Stoldt
General Manager

February 13, 2023



Downed Trees



Debris Piles



Devegetated Banks



Debris “Strainers”



Sand Deposition – San Carlos Bridge



Cobble Deposition and Devegetation



Acre-Feet Past Highway 1 Gauge

	OCT	NOV	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	TOTAL
2017	632	1,047	3,412	68,938	75,173	20,383	13,426	6,732	3,270	1,646	920	712	196,291
2023	92	20	6,580	84,820									