

Consider Expenditure of Funds  
for the Maintenance and Repair  
of the Rearing Channel Liner at  
the Sleepy Hollow Steelhead  
Rearing Facility

# Rearing Channel Liner (Originally Installed in 1996)



# Damaged liner at the end of the channel



# Rearing Channel Leak

